

Duneland Schools Water Testing Remediation Results

TEST LOCATION	FIXTURE	INITIAL TEST RESULTS	RESULTS RECEIVED	REMEDICATION #1	RETEST RESULTS	RETEST RESULTS RECEIVED	REMEDICATION #2	RETEST RESULTS	RETEST RESULTS RECEIVED
CHESTERTON HIGH SCHOOL									
Room 528	sink	37.9	5/18/18	removed					
CHESTERTON MIDDLE SCHOOL									
Second Floor Gym	bubbler	19.1	5/18/18	removed					
Second Floor Locker Room	bubbler	26.2	5/18/18	removed					
Outside Concession	spigot	27.6	5/18/18	lead filter installed	0.5	7/23/18			
BAILLY ELEMENTARY SCHOOL									
Room 192	sink	15.2	4/20/18	lines and fixture replaced	8.1	6/12/18			
Gym	bubbler	15.2	4/20/18	removed					
Room 116	bubbler	20.9	4/20/18	removed					
Room 189	sink	30.3	4/20/18	lines and fixture replaced	160	6/11/18	lead filter installed	0.94	7/23/18
YOST ELEMENTARY SCHOOL									
South Hall	fountain	24.9	4/20/18	removed					
Room 107	bubbler	16.2	4/20/18	removed					
Room 109	sink	16.8	4/20/18	removed					
Room 110	fountain	30.3	4/20/18	lines and fixture replaced	24	6/12/18	lead filter installed	0.5	7/23/18
Room 110	sink	26.9	4/20/18	lines and fixture replaced	54	6/12/18	lead filter installed	0.5	7/23/18
Library	sink	52	4/20/18	fixture replaced	12	6/12/18			
Room 108	sink	118	4/20/18	removed					
WESTCHESTER INTERM. SCHOOL									
North Hall	fountain	16.6	3/23/18	removed					
Kitchen	south sink	17.7	3/23/18	fixture replaced	70	5/2/18	lines replaced	3.1	5/15/18
Kitchen	north sink	17.3	3/23/18	fixture replaced	21	5/2/18	lines replaced	1.7	5/15/18
Media Office	sink	19.7	3/23/18	removed					
PTO Room 109	sink	26	3/23/18	removed					
PTO Room 109	sink	27.2	3/23/18	removed					
PTO Room 109	sink	32.5	3/23/18	removed					
PTO Room 109	sink	37.7	3/23/18	removed					
LIBERTY INTERM. SCHOOL									
North Hall	fountain	20.5	3/23/18	new fixture	1.2	5/3/18			
Music Hall	fountain	25	3/23/18	removed					
Room 105	sink	46.8	3/23/18	removed					
122a Mail Hall	fountain	50.8	3/23/18	new fixture	0.5	5/3/18			
123b Main Hall	fountain	59	3/23/18	new fixture	0.5	5/3/18			
117b Main Hall	fountain	65.7	3/23/18	new fixture	1.2	5/15/18			
Art Hall	fountain	84.5	3/23/18	new fixture	2.5	5/15/18			
Library Hall	fountain	188	3/23/18	new fixture	0.5	5/15/18			
LIBERTY ELEMENTARY SCHOOL									
Room 152	sink	16.8	4/11/18	new fixture	1.1	5/15/18			
Room 152	fountain	21	4/11/18	new fixture	6.9	5/15/18			
Kitchen Hot	sink	23.4	4/11/18	new fixture	55	5/2/18	replace lines	0.9	5/22/18
Room 172	sink	36.6	4/11/18	new fixture	9.5	5/15/18			
Room 173	sink	46	4/11/18	new fixture	1.4	5/15/18			
Room 158	sink	68.9	4/11/18	new fixture	9.5	5/15/18			
Room 203	sink	98.2	4/11/18	new fixture	55	5/15/18	lead filter installed	0.5	7/23/18
Room 176	sink	220	4/11/18	new fixture	0.81	5/15/18			
Room 170	sink	670	4/11/18	new fixture	12	5/15/18			